

[Feb-2019220-901 Dumps in VCE and PDF New Updated By Braindump2go(Q1391-Q1401)

2019/February Braindump2go CompTIA A+ 220-901 Exam Dumps with PDF and VCE New Updated Today! Following are some new 220-901 Real Exam Questions:1.|2019 Latest 220-901 Exam Dumps (PDF & VCE) 1513Q&As Instant Download:<https://www.braindump2go.com/220-901.html>2.|2019 Latest 220-901 Exam Questions & Answers Instant Download:<https://drive.google.com/drive/folders/127R-FUJ-HglYUMe-cATsYTTlqyzyUTB?usp=sharing>**QUESTION 1391**Which of the following does a DHCP server provide to a domain-connected computer? (Choose two.)A. Print servicesB. Host servicesC. IP addressD. DNS server addressE. CDFS**F. POST service****Answer: CD****QUESTION 1392**A user is having intermittent problems connecting a computer to the office network. A technician determines the computer's network cable needs to be replaced. Which of the following tools did the technician use to determine the issue?A. Cable toner probeB. Cable stripperC. Cable testerD. WIFI analyzer**Answer: C****QUESTION 1393**A sales representative is planning a business trip that will involve stays at hotels in remote location with little broadband and poor cellular reception. Which of the following does the IT department need to ensure is available on the sales representative's laptop for reliable telecommunicating while travelling?A. RJ-45 jackB. Bluetooth capabilityC. RJ-11 jackD. PCMCIA card**Answer: C****QUESTION 1394**A customer is looking for a device with high brightness and contrast but can maintain battery life for at least a week. The device will be used exclusively to consume content. Which of the following device types would BEST meet these criteria?A. PhabletB. E-readerC. SmartphoneD. Tablet**Answer: B****QUESTION 1395**A user reports that a PC monitor does not look correct. The user tried adjusting the settings, but the on- screen appearance worsened. The technician inspects the monitor and notices the left and right sides are concave. Which of the following adjustments would MOST likely fix the monitors issue?A. CenteringB. GammaC. TrapezoidD. Pin cushion**Answer: D****QUESTION 1396**Ann, a customer, is in an area where internet connectivity is available. When trying to access a web page on her laptop, she receives "A page cannot be found" message. Which of the following is the FIRST key Ann should check to troubleshooting the internet connection?A. Cellular function keyB. GPS function toggleC. WLAN function toggleD. Bluetooth function key**Answer: C****QUESTION 1397**A 27 in (68.6 cm) analog monitor display shows the left and right sides are bulging outward. Which of the following should the technician performance FIRST to remedy the issue?A. Decrease contrast.B. Increase trapezoid.C. Increase gamma.D. Decrease pin cushion.**Answer: D****QUESTION 1398**When working on a computer that supports triple-Channel memory configurations, which of the following RAM modules would provide the BEST memory performance?A. 2 DIMMsB. 4DIMMsC. 6DIMMsD. 8DIMMs**Answer: C****QUESTION 1399**Joe, a user, recently purchased a new multifunction printer and attempted to installed it himself He informed a technician that the printer is on his list of printers, but he is unable to print. The technician sees that printer is listed printer under devices and printers. Which of the following should the technician do NEXT?A. Reboot the computer into safe mode and try to printer a test page.B. Download the correct drives from the manufacture's website and install them.C. Unplug the USB cable from the printer and try another USB slot the PC.D. Set the printer as the default within the device properties.**Answer: B****QUESTION 1400**A musician asks for help with connection two MIDI devices to a computer. The computer has one MIDI-in and one MIDI-out port. Which of the following explains how the connections should be made?A. Connect the computer MIDI port ton each of the two devices, creating a line configuration.B. Connect each MIDI-out to the MIDI-in on another device, creating a circle configuration.C. The connections cannot be made due to an insufficient number of ports.D. Connect one device at a time to the computer and move the connections when the other device is needed.**Answer: B****QUESTION 1401**Which of the following is considered the I/O controller hub?A. SouthbridgeB. CPU socketC. Front-side busD. PCIe slot**Answer: A**!!!RECOMMEND!!!1.|2019 Latest 220-901 Exam Dumps (PDF & VCE) 1513Q&As Instant Download:<https://www.braindump2go.com/220-901.html>2.|2019 Latest 220-901 Study Guide Video Instant Download: YouTube Video: [YouTube.com/watch?v=H3mpGcn_yYw](https://www.youtube.com/watch?v=H3mpGcn_yYw)